




Completed parlour building




Steel frame for the new parlour building



View from the southern side of the dairy complex



The dairy complex during construction



Steel frame structure of all 3 buildings, and adjoining walkway



Dairy complex during construction




Installation of the rotary parlour



Construction of the rotary parlour

PARLOUR BUILDING




Parlour Building Elevations




New rotary parlour in use



Parlour building once completed




Building 1 - Parlour and Collecting Yard
Building 2 - Animal Housing Cubicles and Straw Bedding
Building 3 - Animal Housing, All Cubicles



Cubicle building 2, showing specialist parlour feeders under the sheltered walkway




South end of the cubicle building, with 2 drive motors for the scrapers




Structural Detail

North end of the cubicle



Cubicle Building Elevations



Steel frame of cubicle building no. 1



View along the east edge of cubicle building no. 1



Cubicle 1 when first completed



View along side of cubicle building 1




View from south end of cubicle building no. 1

CUBICLE BUILDING 1



Elevations of cubicle building no. 1



Cubicle building 1, section and elevations




Cubicle 2, self locking yokes



View looking down the edge scraper passage of cubicle 2

CUBICLE BUILDING 2


Cubicle building 2, section and elevations



Building 3, Section



Building 3, South Elevation




Building 3, North Elevation



Views of cubicle 1 now in use



View down scraper passage on east side of the building



Steel frame of cubicle building no. 2



Specialist parlour feeders on cubicle 2